

BELZONA PUMP DIFFUSER PROTECTED

ID: 163

Industry: *Water / Wastewater*

Customer Location: *Sewage Treatment Plant in Northern California*

Application: *CEP-Centrifugal Pumps*

Application Date: *September 1982*

Substrate: *Cast iron*

Products: ** Belzona® 1311 (Ceramic R Metal) Belzona® 1321 (Ceramic S Metal) ,*

Problem

Erosion/corrosion and cavitation



Photograph Descriptions

- * The diffuser removed for repairs ,
- * Damage on flow surface ,
- * Close up of cavitation pitting ,
- * Repairs in progress using a rotating jig to create the internal shape and dimension without machining ,

Application Situation

Centrifugal pump diffuser

Application Method

The application was carried out in accordance with Belzona Know-How Leaflets CEP-1 and CEP-2.

Belzona Facts

This pump was in service for seven years with no damage until the unit was removed from service for other reasons. Extending the life of the pump diffuser saved the plant tremendous replacement costs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve