

BELZONA SEALS PLANT ROOM FLOOR

ID: 1637

Industry: Buildings & Structures
Application: CEP-Centrifugal Pumps
Substrate: Concrete
Products: * Belzona® 5231 (SG Laminate) ,

Customer Location: Hospital, UK
Application Date: May 2009

Problem

Water was leaking through the floor to the operating theatres below.



Photograph Descriptions

* Damaged floor Belzona® 5231 application starting Completed application Completed application ,

* ,

Application Situation

Boiler plant room of a hospital

Application Method

Application was carried out in accordance with Belzona Know How System Leaflet FPA-8. The floor was first diamond ground and then two coats of Belzona® 5231 (SG Laminate) applied.

Belzona Facts

The whole application was carried out over one weekend. The low odour, solvent free Belzona® 5231 did not impact on normal operating of the hospital.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve