

BELZONA REPAIRS LEAKING SCHOOL ROOF

ID: 1649

Industry: *General Industry*
Application: *RPA-Roof Problem Areas*
Substrate: *Zinc*
Products: ** Belzona® 3131 (WG Membrane) ,*

Customer Location: *Public school, UK*
Application Date: *July 2009*

Problem

The roof was leaking at the joints, seams and gutters.



Photograph Descriptions

- * Prior to application ,
- * Roof part 1, the completed application ,
- * Roof part 2 before application ,
- * Roof part 2 completed ,

Application Situation

Low pitch zinc sheet roof at school.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets RPA-1 & 6.

Belzona Facts

On this roof the College required coloured demarcation of no walk zones (light grey) and walkways (dark grey) across the roof for the maintenance teams to access the plant and clean gutters safely.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve