

BELZONA REPAIRS SUN DAMAGE ON ROOF

ID: 168

Industry: General Industry

Customer Location: Railway Engineering Workshops in Northern England

Application: RPA-Roof Problem Areas


Application Date: June 1996

Substrate: Concrete treated with bitumen

Products: * Belzona® 3111 (Flexible Membrane),

Problem

Leaks at seams, bituminous coating is damaged



Photograph Descriptions

- * Failed bituminous coating ,
- * Seam areas addressed ,
- * Ducting completely protected and sealed ,

Application Situation

Extraction Ducting

Application Method

The application was carried out in accordance with Belzona Know-How Leaflet RPA-1.

Belzona Facts

The tar was severely damaged due to the effects of the sun; further application of the bituminous coating would have also failed. Belzona® 3111 (Flexible Membrane) solved the problem on the roof.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024