

# BELZONA REPAIRS SUN DAMAGE ON ROOF

ID: 168

**Industry:** *General Industry*

**Customer Location:** *Railway Engineering Workshops in Northern England*

**Application:** *RPA-Roof Problem Areas*

**Application Date:** *June 1996*

**Substrate:** *Concrete treated with bitumen*

**Products:** *\* Belzona® 3111 (Flexible Membrane),*

## Problem

*Leaks at seams, bituminous coating is damaged*



## Photograph Descriptions

- \* Failed bituminous coating ,
- \* Seam areas addressed ,
- \* Ducting completely protected and sealed ,

## Application Situation

Extraction Ducting

## Application Method

The application was carried out in accordance with Belzona Know-How Leaflet RPA-1.

## Belzona Facts

The tar was severely damaged due to the effects of the sun; further application of the bituminous coating would have also failed. Belzona® 3111 (Flexible Membrane) solved the problem on the roof.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve