

BELZONA REPAIRS COLOUR MATCH SPALLED LINTELS

ID: 1681

Industry: Buildings & Structures
Application: WPA-Wall Problem Areas
Substrate: Concrete
Products: * Belzona® 4141 (Magma Build) ,

Customer Location: Local Education Authority, UK
Application Date: September 2009

Problem

Spalled concrete due to rebar corrosion.



Photograph Descriptions

- * Spalled concrete. ,
- * Application in process using straight edge to form neat corner. ,
- * Completing the application. ,
- * Completed application. Note excellent colour match. ,

Application Situation

Concrete lintels.

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet WPA-4. Belzona® 4141 was colour matched to existing concrete using Iron Oxide pigments.

Belzona Facts

Repair was carried out quickly without need for scaffolding or permanent shuttering. Ability to colour match the repair ensured aesthetic acceptability.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve