

BELZONA REFURBISHES THE FLOORS

ID: 169

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4131 (Magma Screed) ,

Customer Location: Airport Food Service in Missouri
Application Date: February 1996

Problem

Water was trapped under the tile, causing the tile to break up and providing a haven for bacteria and mold. Pushing the carts over rough, broken, and missing tile posed a serious safety hazard as well.



Photograph Descriptions

- * Removing old tile, dirt and concrete ,
- * Beginning application of Belzona® 4131 (Magma Screed) ,
- * Job almost completed ,

Application Situation

Wash area floor for aircraft food service carts

Application Method

Old concrete was removed and 1 1/2" voids were left in several areas. Belzona® 4131 (Magma Screed) was applied over the areas where the minimum depth was 3/8". The application was carried out in accordance with Belzona Know-How Leaflet FPA-1.

Belzona Facts

The application covered a 72 square foot area and took only two hours to complete. The wash area is now a safer and cleaner place to work.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve