

# BELZONA REFURBISHES THE FLOORS

ID: 169

Industry: General Industry  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona® 4131 (Magma Screed) ,

Customer Location: Airport Food Service in Missouri  
Application Date: February 1996

## Problem

Water was trapped under the tile, causing the tile to break up and providing a haven for bacteria and mold. Pushing the carts over rough, broken, and missing tile posed a serious safety hazard as well.



## Photograph Descriptions

- \* Removing old tile, dirt and concrete ,
- \* Beginning application of Belzona® 4131 (Magma Screed) ,
- \* Job almost completed ,

## Application Situation

Wash area floor for aircraft food service carts

## Application Method

Old concrete was removed and 1 1/2" voids were left in several areas. Belzona® 4131 (Magma Screed) was applied over the areas where the minimum depth was 3/8". The application was carried out in accordance with Belzona Know-How Leaflet FPA-1.

## Belzona Facts

The application covered a 72 square foot area and took only two hours to complete. The wash area is now a safer and cleaner place to work.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve