

BELZONA ATTENTION ON THE ROOF

ID: 172

Industry: General Industry
Application: RPA-Roof Problem Areas
Substrate: Conventional four ply build up roof and brick
Products: * Belzona® 3111 (Flexible Membrane) ,
* Belzona® 9311 (Membrane Reinforcing Sheet) ,

Customer Location: U.S. Air Force Base in Illinois, USA
Application Date: July 1995

Problem

This building had been renovated, severe leaks were destroying new ceiling tiles and wallpaper. Flashings were pulled away from the wall and water gushed in.



Photograph Descriptions

- * Belzona® 9311 (Membrane Reinforcing sheet) is pre-wetted prior to application. ,
- * Second coat of Belzona® 3111 (Flexible Membrane) over first. ,
- * The finishing touches. ,

Application Situation

Roof

Application Method

The application was carried out in accordance with Belzona Know-How Leaflet RPA-8.

Belzona Facts

240 linear feet by 2 feet wide was coated in five hours. One hour later, a heavy rain blew in, there were no leaks and no damage to the Belzona® 3111 (Flexible Membrane). The roof is now watertight.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve