

BELZONA DOES FLOORS

ID: 186

Industry: *General Industry*

Customer Location: *Beverage Canning Company in Mississippi, U.S.A.*

Application: *TCC-Tanks and Chemical Containment Areas*

Application Date: *January 1996*

Substrate: *Concrete*

Products: ** Belzona® 4131 (Magma Screed) ,*

Problem

Extreme erosion surrounding drains due to acidic water discharge



Photograph Descriptions

- * Application commences, note the erosion of the concrete drain area. ,
- * Application proceeds. ,
- * Finished application, concrete protected and proper drainage restored. ,

Application Situation

Chemical containment floor drainage area

Application Method

Application was carried out in accordance with Belzona Know-How Leaflet TCC-9.

Belzona Facts

Concrete would not hold up to the conditions. To remove the tanks and install a new floor would cost \$60,000 and require 2-3 weeks downtime. Preparation took 8 hours and the application of product took 8 hours. The customer saved \$50,000 by using Belzona.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

www.belzona.com

EMS 695213

Management System.

