

# BELZONA® 4111 MAINTAINS SAFE FACTORY ENVIRONMENT

ID: 202

Industry: *General Industry*  
Application: *TCC-Tanks and Chemical Containment Areas*  
Substrate: *Concrete*  
Products: *\* Belzona® 4111 (Magma-Quartz),*

Customer Location: *Manufacturing plant*  
Application Date: *1978 & 1998*

## Problem

*Leakage of cutting oils, lubricants and printing inks from the machinery create a serious slip and skid hazard.*



## Photograph Descriptions

- \* Former being positioned ,
- \* General view of machines with formed bunds ,
- \* Close-up of the formed bund ,

## Application Situation

Pedestrian and fork lift access areas around production machinery.

## Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet TCC-9.

## Belzona Facts

Three inch plastic half pipes were used to form the Belzona® 4111 thereby creating a bund or containment area around each machine. The Belzona application has withstood heavy duty use and is resistant to the various oils and chemicals in use. The application also has helped to satisfy hygiene inspectors previously concerned with floor contamination.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve