

# BELZONA SEALS SWIMMING POOL LEAKS

ID: 205

Industry:	General Industry	Customer Location:	Municipality
Application:	FPA-Floor Problem Areas	Application Date:	August 1999
Substrate:	Concrete		
Products:	* Belzona® 4111 (Magma-Quartz) , * Belzona® 2211 (MP Hi-Build Elastomer) ,		

## Problem

*The original Silicone sealant had deteriorated allowing large water losses.*



## Photograph Descriptions

- \* General view of the pool ,
- \* Joint nosings rebuilt with tinted belzona® 4111 ,
- \* Joint being masked prior to sealing with Belzona® 2211 ,

## Application Situation

Expansion joints in swimming pool

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-6.

## Belzona Facts

Water losses were estimated to cost \$3,300 per month (replacement, heating and treatment). This type of application has been carried out for 14 years with great success. The Belzona® 4111 is tinted blue, grey and beige to match the pool design.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve