

# BELZONA REFURBISHES SCRUBBER RUBBER

ID: 207

Industry: Power

Customer Location: TVA Powerplant (Tennessee Valley Authority- U.S.A.)

Application: SHM-Solids Handling Machinery

Application Date: July 2000

Substrate: Carbon steel pipe

Products: \* Belzona® 1812 ,

## Problem

Once the rubber was gone, the exposed carbon steel would only last one week.



## Photograph Descriptions

- \* Application begins ,
- \* Application continues ,
- \* Close-up view at a repaired area ,

## Application Situation

Rubber lining on a scrubber unit was worn away leaving carbon steel exposed.

## Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflets SHM-8 and SHM-9.

## Belzona Facts

By utilizing the Belzona solution, wear on the carbon steel pipe was eliminated, thereby reducing maintenance costs and extending the life of the equipment.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve