

# BELZONA SEALS ACCESS RAMP LEAKS

ID: 2086

Industry: Buildings & Structures  
Application: RPA-Roof Problem Areas  
Substrate: Concrete  
Products: \* Belzona® 3111 (Flexible Membrane) ,

Customer Location: Recreation Center, BC, Canada  
Application Date: September 2002

## Problem

The caulking between the walls and ramp base needed to be replaced on a regular basis to prevent water from entering into the area below.



## Photograph Descriptions

- \* View of joint to be sealed ,
- \* Application of 1st coat of Belzona® 3111 incorporating Reinforcement Sheet ,
- \* Completed application ,

## Application Situation

Water was entering the storage and equipment areas below.

## Application Method

Application carried out in accordance with Belzona Know-How System Leaflet RPA-1.

## Belzona Facts

Belzona® 3111 Flexible Membrane was used to create a flexible flashing between the wall and floor eliminating the previous repetitive maintenance with sealants.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve