

BOILING WATER: NO PROBLEM FOR BELZONA® 4181

ID: 210

Industry: *General Industry*
Application: *FPA-Floor Problem Areas*
Substrate: *Concrete*
Products: ** Belzona® 4181 ,*

Customer Location: *Hospital*
Application Date: *July 2000*

Problem

Boiling water had broken down an existing epoxy coating and the underlying concrete floor it was supposed to protect.



Photograph Descriptions

- * General view of floor problem area ,
- * Close-up of damaged area around drainage channel ,
- * Belzona® 4181 application underway ,
- * The finished application ,

Application Situation

Hospital kitchen floor

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & FPA-3.

Belzona Facts

The area was tented to protect the surrounding area and the remaining coating was removed. Belzona® 4181 was able to withstand the boiling water and is now being considered for other application areas.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve