

# BELZONA REPARÉ LES FUITES D'HUILE SUR LES AILETTES D'UN TRANSFORMATEUR

ID: 2128

Industrie: *Énergie*

Localisation du client: *Station de distribution électrique, Royaume-Uni*

Application: *Vannes, tuyaux et raccords*


Date de la demande: *2008*

Substrat: *Acier*

Des produits: *\* Belzona 1161 (Super UW-Metal) ,*

## Problem

*Fuites d'huile des ailettes.*



## Descriptions des photographies

\* 1. Vue d'ensemble du transformateur. 2. Vue de près de la zone de fuite de l'huile. 3. Application achevée. Fuite éliminée avec Belzona 1161. ,

## Cas d'application

Transformateur électrique refroidi à l'huile.

## Procédé d'application

L'application a été effectuée en accord avec la procédure Belzona VPF-11a, utilisant un produit Belzona tolérant de l'état de surface

## Faits sur Belzona

Le besoin coûteux de drainer l'huile afin d'effectuer la réparation a été éliminé. La réparation Belzona a été réalisée en moins de 2 heures et s'est avérée être un succès total.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Réparer • Protéger • Améliorer

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

