

# BELZONA PROTECTS NEW STAINLESS STEEL CONES

ID: 213

Industry: *Power*  
Application: *SHM-Solids Handling Machinery*

Customer Location: *Power Plant in Florida, U.S.A.*  
Application Date: *October 2000*

Substrate: *Stainless steel*  
Products: *\* Belzona® 1812 ,*

## Problem

*Impact and abrasion from coal, coupled with high temperatures caused severe wear to the cone walls.*



## Photograph Descriptions

- \* New cone prior to application ,
- \* Blasted cones ,
- \* Protected cone with Belzona® 1812 that is ready for service ,

## Application Situation

Transition cones from conveyor belts to coal pulverizers.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-13.

## Belzona Facts

The plant had been replacing the cones every five years with difficult access. Belzona® 1812 offered great flexibility to their program by providing long term protection against premature wear.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve