

# BELZONA® 3111 PROVEN PERFORMANCE

ID: 215

Industry: *Chemical & Petrochemical*  
 Application: *RPA-Roof Problem Areas*  
 Substrate: *Asbestos and asphalt*  
 Products: *\* Belzona® 3111 (Flexible Membrane) ,*

Customer Location: *Chemical plant in the United Kingdom*  
 Application Date: *1986 and 1988*

## Problem

*Severe water penetration, particularly through joints, seams, glazing units and gutters.*



## Photograph Descriptions

- \* Work underway on the workshop roof ,
- \* Horizontal area of office roof undergoing treatment ,
- \* Completed application ,

## Application Situation

Roof areas over offices and workshops.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, RPA-3 and RPA-6.

## Belzona Facts

Belzona was chosen over other materials as previous repairs with competitive materials on the site had underperformed. Belzona system lived up to expectations and was in excellent condition when inspected in 1997.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
 FS 695214  
 ISO 14001:2015  
 EMS 695213

Belzona products are  
 manufactured under an ISO  
 9000 Registered Quality  
 Management System.

[www.belzona.com](http://www.belzona.com)