

BELZONA RAPID REPAIR TO VIADUCT RAILING SUPPORT

ID: 2161

Industry: *General Industry*

Customer Location: *Town council, Canada*

Application: *FPA-Floor Problem Areas*

Application Date: *May 2003*

Substrate: *Concrete and steel*

Products: ** Belzona® 4141 (Magma-Build) ,*

Problem

The concrete base for railings support pillars was cracked and spalled.



Photograph Descriptions

* Concrete condition before the application The concrete is coated with Belzona® 4911 Conditioner Belzona® 4141 application completed quickly and easily without the use of formwork ,

Application Situation

Pedestrian pavement beneath viaduct.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-10.

Belzona Facts

The application was achieved in 2 hours and without the need for any formwork. This application is still in excellent condition when inspected in 2011.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com