

# BELZONA RAPID REPAIR TO VIADUCT RAILING SUPPORT

ID: 2161

Industry: *General Industry*  
 Application: *FPA-Floor Problem Areas*  
 Substrate: *Concrete and steel*  
 Products: *\* Belzona® 4141 (Magma-Build) ,*

Customer Location: *Town council, Canada*  
 Application Date: *May 2003*

## Problem

*The concrete base for railings support pillars was cracked and spalled.*



## Photograph Descriptions

\* Concrete condition before the application The concrete is coated with Belzona® 4911 Conditioner Belzona® 4141 application completed quickly and easily without the use of formwork ,

## Application Situation

Pedestrian pavement beneath viaduct.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-10.

## Belzona Facts

The application was achieved in 2 hours and without the need for any formwork. This application is still in excellent condition when inspected in 2011.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
 FS 695214  
 ISO 14001:2015  
 EMS 695213

Belzona products are  
 manufactured under an ISO  
 9000 Registered Quality  
 Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
 Repair • Protect • Improve