

BELZONA KEEPS WORN HOSE WORKING

ID: 220

Industry: *General Industry*
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Shipping company in Canada*
Application Date: *November 2000*

Substrate: *Rubber*
Products: ** Belzona® 2311 (SR-Elastomer),*

Problem

The uploading cement hose had worn through to the reinforcement wire.



Photograph Descriptions

- * Overview of damaged area ,
- * Loose pieces have been removed ,
- * The conditioner, reinforcement sheet and Belzona® 2311 (SR-Elastomer) have been used to fill area ,
- * The finished repair ,

Application Situation

Worn rubber hose

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

Belzona Facts

A quick reliable repair was required and other than replacement, Belzona was the only option.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
Q 09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve