BELZONA REFURBISHES STEPS AT HISTORIC COLLEGE

ID: 2299

Industry: Buildings & Structures Customer Location: College, Oxford, UK
Application: FPA-Floor Problem Areas Application Date: September 2011

Substrate: Stone

Products: * Belzona® 4131 (Magma Screed),

Problem

The steps had worn badly over the last few hundred years. The main contractor had to find a product that they could apply in the evening shift so the staircases could be re-opened ready for the busy work force in the morning to carry on with the rest of the project. The contractor only had six weeks to complete the total College refurbishment.









Photograph Descriptions

- * Worn steps before the application,
- * Steps during the preparation,
- * Steps rebuilt back to profile,
- * Completed application ready for the overlay of carpet,

Application Situation

The College was undergoing a complete refurbishment of the student accommodation area. Part of the work was to rebuild the two staircases at both ends of the building.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

Belzona Facts

The contractor chose Belzona as he had previous experience with the products and knew he could have the stairs repaired and back in service in the short time available. The excellent wear characteristics will also ensure steps do not require repair in the forseable future

www.belzona.com