

BELZONA SEALS EXPANSION JOINTS

ID: 238

Industry: Sugar
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 2221 (MP Fluid Elastomer) ,

Customer Location: Sugar Beet mill in Minnesota, U.S.A.
Application Date: 1991

Problem

Contact with chemicals and sugar juice deteriorate expansion joint sealing material.



Photograph Descriptions

- * Severely damaged expansion joints ,
- * Cleaned and prepared expansion joint before the use of Belzona® 2221 ,
- * Successfully sealed expansion joints ,

Application Situation

Expansion joints in sugar processing facility.

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflets FPA-6.

Belzona Facts

The use of an appropriate expansion joint sealant prevents maintenance shutdowns and conserves the integrity of floor areas.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve