

# BELZONA SEALS EXPANSION JOINTS

ID: 238

Industry: Sugar  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona® 2221 (MP Fluid Elastomer) ,

Customer Location: Sugar Beet mill in Minnesota, U.S.A.  
Application Date: 1991

## Problem

Contact with chemicals and sugar juice deteriorate expansion joint sealing material.



## Photograph Descriptions

- \* Severely damaged expansion joints ,
- \* Cleaned and prepared expansion joint before the use of Belzona® 2221 ,
- \* Successfully sealed expansion joints ,

## Application Situation

Expansion joints in sugar processing facility.

## Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflets FPA-6.

## Belzona Facts

The use of an appropriate expansion joint sealant prevents maintenance shutdowns and conserves the integrity of floor areas.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve