

BELZONA PROTECTS PIPELINE AND VALVES FROM CEMENT ABRASION

ID: 2455

Industry: *General Industry*
Application: *VPF-Valves, Pipes and Fittings*
Substrate: *steel*
Products: ** Belzona® 1811 (Ceramic Carbide),*

Customer Location: *Cement producer, Slovakia*
Application Date: *2000*

Problem

There was high abrasion caused by cement leading to local material loss of metal from valve body.



Photograph Descriptions

- * Badly eroded valve ,
- * Grit blasting the valves ,
- * Completed valve body ,
- * Re-assembled valve protected with Belzona® 1811 ,

Application Situation

Pipes and valves used to transport cement dust.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11.

Belzona Facts

The Belzona solution was initially accepted by customer because repair took only a few hours and the mill shut-down was very short. Since the first repairs in 2000 many more of these repairs have been completed.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve