

BELZONA STOPS FLOOR DRAIN LEAKS




ID: 2458

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: stainless steel, concrete, ceramic tiles
Products: * Belzona® 4111 (Magma Quartz) ,

Customer Location: Machinery manufacturer, Slovakia
Application Date: 2008

Problem

Leakage from the floor drains was problem from the start. Connection between steel and tiles was faulty. Result was the leakage to the next floor.



Photograph Descriptions

- * Situation before repair ,
- * Situation at the floor below ,
- * Surface preparation being carried out ,
- * Belzona® 4111 in place creating a watertight seal ,

Application Situation

Drain in kitchen floor.

Application Method

Application carried out in accordance with the Belzona Know-How System Leaflet FPA-1

Belzona Facts

Customer had tried several alternatives to repair the drain but none worked. Repair with Belzona® 4111 ensured necessary water tightness due to excellent adhesion to different substrates and non-shrink properties.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve