

# BELZONA STOPS FLOOR DRAIN LEAKS

ID: 2458

**Industry:** General Industry  
**Application:** FPA-Floor Problem Areas  
**Substrate:** stainless steel, concrete, ceramic tiles  
**Products:** \* Belzona® 4111 (Magma Quartz) ,

**Customer Location:** Machinery manufacturer, Slovakia  
**Application Date:** 2008

## Problem

Leakage from the floor drains was problem from the start. Connection between steel and tiles was faulty. Result was the leakage to the next floor.



## Photograph Descriptions

- \* Situation before repair ,
- \* Situation at the floor below ,
- \* Surface preparation being carried out ,
- \* Belzona® 4111 in place creating a watertight seal ,

## Application Situation

Drain in kitchen floor.

## Application Method

Application carried out in accordance with the Belzona Know-How System Leaflet FPA-1

## Belzona Facts

Customer had tried several alternatives to repair the drain but none worked. Repair with Belzona® 4111 ensured necessary water tightness due to excellent adhesion to different substrates and non-shrink properties.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve