

BELZONA SECURES DANGEROUS WALKING AREAS

ID: 2476

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Tiles
Products: * Belzona® 4411 (Granogrip) ,

Customer Location: Municipal building, France
Application Date: 2004

Problem

The stairs and walkways, located outside, were very slippery when wet.



Photograph Descriptions

- * The external staircase ,
- * Completed application on the stairs ,
- * Application in progress on the walkways using stencil to create pattern ,
- * Completed application on the walkway ,

Application Situation

Stairs and walkway areas accessing a municipal building.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona® 4411 was applied on stair treads and floor, using stencils to create non slip patterns on each tile.

Belzona Facts

This solution created a durable non-slip surface on the tiled floor whilst at same time presenting an aesthetically acceptable appearance.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025