

## BELZONA REPLACES NON-SLIP TAPES ON RAMP

ID: 2479

Industry: *Buildings & Structures*  
 Application: *FPA-Floor Problem Areas*  
 Substrate: *Travertine stone*  
 Products: *\* Belzona® 4411 (Granogrip),*

Customer Location: *Hospital, France*  
 Application Date: *February 2003*

### Problem

*The ramp was a potential slip hazard and adhesive tapes had been unsuccessfully used to create a non-slip surface. A more positive, long term solution was required.*



### Photograph Descriptions

- \* Ramp with failed tape system clearly evident ,
- \* Ramp after application of Belzona® 4411 ,
- \* Close view of the application ,
- \* General view of the ramp at the hospital entrance ,

### Application Situation

Ramp made of travertine stone.

### Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

### Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
 FS 695214  
 ISO 14001:2015  
 EMS 695213

Belzona products are  
 manufactured under an ISO  
 9000 Registered Quality  
 Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
 Repair • Protect • Improve

After the application, the ramp is as new and safe for pedestrians. This application is reported to still be in perfect condition in 2012.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

