

BELZONA REPLACES NON-SLIP TAPES ON RAMP

ID: 2479

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Travertine stone
Products: * Belzona® 4411 (Granogrip) ,

Customer Location: Hospital, France
Application Date: February 2003

Problem

The ramp was a potential slip hazard and adhesive tapes had been unsuccessfully used to create a non-slip surface. A more positive, long term solution was required.



Photograph Descriptions

- * Ramp with failed tape system clearly evident ,
- * Ramp after application of Belzona® 4411 ,
- * Close view of the application ,
- * General view of the ramp at the hospital entrance ,

Application Situation

Ramp made of travertine stone.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

After the application, the ramp is as new and safe for pedestrians. This application is reported to still be in perfect condition in 2012.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

