# BELZONA PROTECTION OF WATER INJECTION SPOOLS

ID: 248

Industry: Oil & Gas Customer Location: Oil producer in Oman

Application: VPF-Valves, Pipes and Fittings Application Date: May 2000

Substrate: Steel

Products: \* Belzona® 1341 (Supermetalglide),

#### Problem

Severe erosion/corrosion on internal of pipe spools due to brackish water which contains sand and H2S.









#### **Photograph Descriptions**

- \* Spools for coating,
- \* Application underway,
- \* Completed application,
- \* Completed application,

#### **Application Situation**

Water injection header designed to operate up to 50°C.

## **Application Method**

The application was carried out in accordance with Belzona Know-How System Leaflet VPF-2.

### **Belzona Facts**

Belzona has been protecting this type of equipment for several years. The life cycle of the spools is extended and overall maintenance reduced.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve