

BELZONA SPECIFIED PROTECTION OF SOAP PLODDERS

ID: 250

Industry: *General Industry*

Customer Location: *International soap manufacturer - Malaysia*

Application: *SHM-Solids Handling Machinery*

Application Date: *1999*

Substrate: *Aluminium alloy*

Products: ** Belzona® 1391 ,*

Problem

Wear and chemical attack of the worm's surface.



Photograph Descriptions

- * General view of plodder worm after cleaning ,
- * Application underway ,
- * Completed application ,

Application Situation

Silumin worms from soap plidders used in the manufacture of soap.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-14.

Belzona Facts

This customer had tried many alternatives to protect these worms, which are used worldwide. With the success of Belzona, they have standardized the use of Belzona® 1391 as the only material capable of operating in the harsh conditions.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

