

BELZONA® 5811 REPEAT TANK APPLICATION


ID: 264

Industry: *General Industry*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Steel*
Products: ** Belzona® 5811 (Immersion Grade),
* Belzona® 5981,*

Customer Location: *Aluminium producer in Holland*
Application Date: *1993 and February 2001*

Problem

Corrosion under base of original tank necessitated fabrication and protection of new tank.



Photograph Descriptions

- * The first coat of Belzona® 5811 (beige) applied and details being stripe coated ,
- * Second coat of Belzona® 5811 (black) applied ,
- * Tank re-installed in original position ,

Application Situation

Tank used to retrieve lost raw material from ventilation system. Contains sea water and alum earth.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-5. After stripe coating welds, brackets and other awkward areas. The Belzona® 5811 was applied by heated airless spray.

Belzona Facts

Belzona® 5811 originally applied to tank in 1993 was still in excellent condition. However, the tank had corroded on the outside between base and concrete so a new tank had to be fabricated. The client had no hesitation in specifying Belzona® 5811 again.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA®**
Repair • Protect • Improve