BELZONA PROTECTS AMINE REBOILER

ID: 2686

Industry: Oil & Gas

Application: TCC-Tanks and Chemical Containment

Areas

Substrate: Steel

Products: * Belzona® 1511 (Super HT Metal),

* Belzona® 1591 (Ceramic XHT Metal),

Problem

Internal corrosion with heavy pitting in areas.







Customer Location: Gas terminal, UK

Application Date: November 2011



Photograph Descriptions

- * Interior of vessel before blasting,
- * Large areas of pitting,
- * Vessel before application of first coat Belzona® 1591,
- * Coated vessel before final remedial work carried out,

Application Situation

Amine reboiler vessel

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5. Belzona® 1511 was used to fill in pitting. Belzona 1591 applied for overall corrosion protection.

Belzona Facts

Belzona products provide outstanding corrosion protection to the hot chemicals involved. Application was carried out in-situ and with a fast back to service time.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair - Protect - Improve