

BELZONA MAKES FUELING AREAS SAFER

ID: 276

Industry: General Industry

Customer Location: St Lucie County, Florida Schools -
Maintenance Dept.

Application: FPA-Floor Problem Areas

Application Date: January 2002

Substrate: Painted concrete

Products: * Belzona® 4411 (Granogrip) ,

Problem

Bus refueling station had several workman's compensation claims from employees slipping at pump areas.



Photograph Descriptions

- * An overview of the pump station ,
- * A pump prior to the application ,
- * Spills can be seen where the non-skid system has been applied ,
- * A close up of the completed application ,

Application Situation

Fuel pump area

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

Belzona Facts

Belzona® 4411 had already proven to be durable and effective in a heavy traffic area at the bus garage. This application at the refueling station relieved the demands from the workman's compensation authorities, who mandated that the pump area be made more safe or that they hire attendants who are exempt from workman's compensation.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024


BELZONA®
Repair • Protect • Improve