

# BELZONA MAKES FUELING AREAS SAFER

ID: 276

Industry: *General Industry*

Customer Location: *St Lucie County, Florida Schools -  
Maintenance Dept.*

Application: *FPA-Floor Problem Areas*

Application Date: *January 2002*

Substrate: *Painted concrete*

Products: *\* Belzona® 4411 (Granogrip) ,*

## Problem

*Bus refueling station had several workman's compensation claims from employees slipping at pump areas.*



## Photograph Descriptions

- \* An overview of the pump station ,
- \* A pump prior to the application ,
- \* Spills can be seen where the non-skid system has been applied ,
- \* A close up of the completed application ,

## Application Situation

Fuel pump area

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

## Belzona Facts

Belzona® 4411 had already proven to be durable and effective in a heavy traffic area at the bus garage. This application at the refueling station relieved the demands from the workman's compensation authorities, who mandated that the pump area be made more safe or that they hire attendants who are exempt from workman's compensation.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

