

Belzona Restores Safety to Fire Escape Stairway

ID: 2777

Industry: Water / Wastewater
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4411 (Granogrip) ,

Customer Location: Water Supplier, UK
Application Date: April 2011

Problem

The concrete steps had worn and the current safety grip system had become almost none existent due to heavy foot traffic and weathering. A member of staff had slipped down the steps and injured themselves so solution to this serious slip hazard required.



Photograph Descriptions

- * Staircase prior to application ,
- * Surface prepared ready of application ,
- * Completed Application ,
- * Completed Application ,

Application Situation

Smooth concrete fire escape stairway

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona® 4411 in grey was applied to the steps with Belzona® 9221 (Surefoot White Aggregate) incorporated into the main step areas and Belzona 9231 (Surefoot Aggregate) incorporated into the coating on the nosings.

Belzona Facts

The client was looking for a quick solution to overcome this safety issue and selected the Belzona solution as Belzona system offered not only a quick but also long term solution. The application was completed within 3 weeks with minimal disruption to employees and is now providing a safe well gripped fire escape.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

