

# BELZONA NON-SKID SYSTEM REMOVES SLIP AND FALL HAZARD

ID: 289

**Industry:** General Industry  
**Application:** FPA-Floor Problem Areas  
**Substrate:** Quarry Tile  
**Products:** \* Belzona® 1321 (Ceramic S- Metal) ,  
\* Belzona® 9221 (Surefoot Aggregate) ,

**Customer Location:** Hospital in British Columbia, Canada  
**Application Date:** 1997

## Problem

*The floor was plagued with constant complaints arising from slippery floor tiles. Non-skid tape safety pads were in use in strategic areas, but were constantly delaminating from the wet environment and harsh cleaning chemicals.*



## Photograph Descriptions

- \* Surface preparation with template ,
- \* Glaze removed from quarry tile floor ,
- \* Masking tape removed after the application is complete ,
- \* Completed application of grip system ,

## Application Situation

Quarry tiled floor in a hospital dish washing area.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

## Belzona Facts

It was found that the Belzona system initially cost about 30% more, but eliminated the need for replacement pads. The application has been in service for 5 years with no required maintenance.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve