

BELZONA FOR THE REPAIR OF STEP NOSINGS

ID: 290

Industry: Buildings & Structures

Customer Location: Furniture manufacturer in North Carolina U.S.A.

Application: FPA-Floor Problem Areas

Application Date: May 2000

Substrate: Concrete

Products: * Belzona® 4111 (Magma Quartz),
* Belzona® 4411 (Granogrip),

Problem

The step nosings leading to a loading area became rounded from constant traffic and improper handtruck usage.



Photograph Descriptions

- * Damage to step nosings ,
- * Belzona® 4911 (TX Conditioner) applied to steps ,
- * Peeling tape off to reveal Belzona® 4411 (Granogrip) ,
- * Completed application ,

Application Situation

Steps at a furniture manufacturing facility leading to a loading area.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

Belzona Facts

The leading edges of steps take a tremendous beating, and the Belzona material has a combination of adhesive as well as the compressive strength in order to provide a long lasting solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve