

# BELZONA KEEPS ENTRANCE WAY STEPS LOOKING GOOD AND SAFE

ID: 292

Industry: Buildings & Structures

Application: FPA-Floor Problem Areas

Substrate: Quarry Tile

Products: \* Belzona® 4411 (Granogrip) ,  
\* Belzona® 9221 (Surefoot Aggregate) ,

Customer Location: Agency building - Houston, Texas U.S.A.

Application Date: April 1985

## Problem

Various non-skid materials had previously been applied to the nosings of these quarry tile steps with no long-term success.



## Photograph Descriptions

- \* Pulling the tape while the Belzona® 4411 is still wet ,
- \* View of entire area ,
- \* Close-up view of completed application ,

## Application Situation

Step nosings along a very visible entrance way.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

## Belzona Facts

Belzona® 4411 (Granogrip) was applied by brush in conjunction with Belzona® 9221 (Surefoot Aggregate) on the nosings of the quarry tile steps. 1/4 inch tape was cut and placed over the grout lines of the tile to simulate the quarry tile appearance. This area is high visibility for visiting dignitaries and tourists, so emphasis was placed on safety and cosmetics.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Copyright © Belzona International Limited 2025