

# BELZONA SUCCESSFULLY REFURBISHES SCHOOL STEPS


ID: 2928

Industry: Buildings & Structures  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona 5811 (Immersion Grade) ,  
\* Belzona 4411 (Granogrip) ,

Customer Location: Warwickshire, UK  
Application Date: May 2011

## Problem

Steps were leaking into a wash room below so needed to be sealed. Also access to the roof was needed so slip hazards had become an issue.



## Photograph Descriptions

- \* 1. Application of Belzona 5811 to walls. ,
- \* 2. Application of Belzona 5811 to steps. ,
- \* 3. Complete encapsulation of steps and walls. ,
- \* 4. Completed application with Belzona 4411 on step noses. ,

## Application Situation

Steps over wash room in school

## Application Method

Application was carried out in accordance with Belzona Know How System Leaflet FPA-8

## Belzona Facts

Repairs were carried out over two days and have now provided the school with waterproof and safe steps. They were so pleased with the results that they had other sets of steps coated with Belzona 4411.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

[www.belzona.com](http://www.belzona.com)

