

BELZONA SUCCESSFULLY REFURBISHES SCHOOL STEPS


ID: 2928

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 5811 (Immersion Grade) ,
* Belzona 4411 (Granogrip) ,

Customer Location: Warwickshire, UK
Application Date: May 2011

Problem

Steps were leaking into a wash room below so needed to be sealed. Also access to the roof was needed so slip hazards had become an issue.



Photograph Descriptions

- * 1. Application of Belzona 5811 to walls. ,
- * 2. Application of Belzona 5811 to steps. ,
- * 3. Complete encapsulation of steps and walls. ,
- * 4. Completed application with Belzona 4411 on step noses. ,

Application Situation

Steps over wash room in school

Application Method

Application was carried out in accordance with Belzona Know How System Leaflet FPA-8

Belzona Facts

Repairs were carried out over two days and have now provided the school with waterproof and safe steps. They were so pleased with the results that they had other sets of steps coated with Belzona 4411.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2025

