

BELZONA REFURBISHES SCHOOL STEPS

ID: 2929

Industry: Buildings & Structures

Application: FPA-Floor Problem Areas

Substrate: Concrete

Products: * Belzona® 5811 (Immersion Grade) ,


* Belzona® 4411 (Granogrip) ,

Customer Location: Warwickshire, UK

Application Date: May 2011

Problem

Steps were allowing water into the wash room below so needed to be sealed. Also access to the roof was needed so elimination of any slip hazards had become an issue.



Photograph Descriptions

- * Application of Belzona® 5811 to walls ,
- * Application of Belzona® 5811 to steps ,
- * Complete encapsulation of steps and wall ,
- * Completed application with Belzona® 4411 on step noses ,

Application Situation

Access steps to roof of school with wash room underneath.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Repairs were carried out over two days and have now provided the school with safe and waterproof steps. Following the success of this repair, the customer has since treated several other steps on the site with Belzona 4411.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

| | |
|----------------|---------------------------|
| ISO 9001:2015 | Belzona products are |
| FS 695214 | manufactured under an ISO |
| ISO 14001:2015 | 9000 Registered Quality |
| EMS 695213 | Management System. |

www.belzona.com

