

BELZONA REPAIRS DAMAGED FLOOR AT CIDER PLANT


ID: 2931

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4131 (Magma Screed) ,
* Belzona® 5231 (SG Laminate) ,

Customer Location: Cider producer, Herefordshire, UK
Application Date: January 2012

Problem

Due to spillage of cider concentrate the concrete floor had begun to break up and created health and safety issues with trips and slips.



Photograph Descriptions

- * Damaged floor ,
- * Application of Belzona® 4131 including conditioner to ensure maximum adhesion ,
- * Complete floor repaired with Belzona® 4131 ,
- * Application of Belzona® 5231 completed ,

Application Situation

Inspection hut floor in cider storage tank area

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. Belzona® 4131 used to repair damaged concrete and level surface before coating with Belzona 5231.

Belzona Facts

Both Belzona® 4131 and Belzona® 5231 have been used many times around the site to protect against the effects of the cider. Alternatives have been tried before but Belzona offers them the best long term solution. The Belzona system used enabled floor to be levelled and then finished with slip resistant hygienic surface.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve