

BELZONA TAKES OFF AT THIS INTERNATIONAL AIRPORT

ID: 294

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Steel reinforced concrete.
Products: * Belzona® 4111 (Magma Quartz) ,

Customer Location: International Airport, U.S.A.
Application Date: 1993

Problem

Certain sections of the runway and ramps were spalled from both thermal cycling as well as mechanical damage from constant aircraft traffic.



Photograph Descriptions

- * Spalled concrete on runway ,
- * Surface prepared by chipping loose concrete ,
- * Conditioned with Belzona® 4911 (Magma TX Conditioner) ,
- * Curing of completed repair being accelerated with heat ,

Application Situation

Landing areas and ramps.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

Belzona Facts

Belzona® 4111 (Magma Quartz) was mechanically mixed after the damaged areas were prepared and thoroughly conditioned. The repair material was hand applied and accelerated with infrared lighting to sufficiently cure in the scheduled four-hour downtime. Nine other repair materials were tried, but all failed because of a combination of slow cure times and poor adhesion characteristics.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve