

BELZONA MAKES WALKWAY SAFE

ID: 2953

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4131 (Magma Screed) ,
* Belzona® 4411 (Granogrip) ,

Customer Location: Cider producer, Herefordshire, UK
Application Date: September 2011

Problem

Delamination of resin floor had caused a trip hazard. When the repair was looked at they noted that there was a slip hazard in the same area.



Photograph Descriptions

- * Trip hazard levelled with Belzona® 4131 ,
- * Application of Belzona® 4411 ,
- * Removal of masking tape ,
- * Completed application. ,

Application Situation

Walkway in production area of Cider Plant

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona® 4131 applied to level floor area before applying Belzona® 4411 grip system.

Belzona Facts

When routine maintenance was carried out they would step out of a small bund with wet feet. Belzona® 4131 ability to be feather edged allowed easy levelling of the walkway. The yellow Belzona® 4411 was chosen as both a positive grip system and as a visual aid.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve