

# BELZONA HELPS TO KEEP WORKSHOP CLEAN AT CIDER PLANT

ID: 2954

Industry: General Industry

Customer Location: Cider Producer, Herefordshire, UK

Application: WPA-Wall Problem Areas

Application Date: June 2011

Substrate: Steel and brick

Products: \* Belzona® 5111 (Ceramic Cladding) ,  
\* Belzona® 5911 (Ceramic Conditioner) ,

## Problem

Customer was looking for a product that they could wipe clean, have chemical resistance and brighten up a dull workshop.



## Photograph Descriptions

- \* Application of Belzona® 5911 Conditioner ,
- \* Application of First Coat of Belzona® 5111 ,
- \* Completed application ,
- \* New brighter, cleaner working area ,

## Application Situation

Engineers workshop in cider plant

## Application Method

Application was carried out in accordance with Belzona System Leaflet WPA-2

## Belzona Facts

Belzona® 5111 was the only product they could find to fill all of their requirements. Its excellent chemical and abrasion resistance allows for easy cleaning enabling clean bright environment to be maintained.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

Q 09335

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 509612

Management System.

[www.belzona.com](http://www.belzona.com)

