

BELZONA REPAIRS DAMAGED CONCRETE AT CIDER PLANT

ID: 2955

Industry: General Industry

Application: FPA-Floor Problem Areas

Substrate: Concrete

Products: * Belzona® 4131 (Magma-Screed) Belzona® 2211 (MP Hi-Build Elastomer) ,

Customer Location: Cider producer, Herefordshire, UK

Application Date: August 2011

Problem

Damaged concrete on walkway was identified as a trip hazard.



Photograph Descriptions

* Previous attempted repair Nosings rebuilt with Belzona® 4131 Application of Belzona Elastomer Conditioner Completed application with joint sealed using Belzona® 2211 ,

Application Situation

Pedestrian crossing at cider plant

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-5 & 6. Damaged joint nosings were reformed with Belzona® 4131 before sealing joint with Belzona® 2211.

Belzona Facts

Other cheaper products had been used to try and fix problem but with no success. Belzona was chosen due to its proven reliability and longevity at other applications around the site. Belzona 4131 provides an impact resistant joint nosing whilst Belzona® 2211 provides strongly bonded highly elastic joint sealant.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024