

BELZONA REFURBISHES SCHOOL ROOF

ID: 2971

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Ashfelt*

Customer Location: *Warwickshire, UK*
Application Date: *September 2011*

Products: ** Belzona 3131 (WG Membrane) ,*
** Belzona 9361 (Reinforcing Sheet) ,*

Problem

Due to age and cracks in both the parapit walls and in the ashfelt the roof was leaking into the classrooms below.



Photograph Descriptions

- * 1. and 2. Before Application ,
- * 3. and 4. After Application ,

Application Situation

Hall/Classroom roof on School

Application Method

Application was carried out in accordance with Belzona System Leaflet RPA-6 and RPA-10

Belzona Facts

School were so happy with the Belzona repair that they have now had another flat roof coated and some steps repaired with Belzona.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve