

HOSPITAL KITCHEN REPAIRED WITH BELZONA

ID: 298

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Quarry tile and concrete
Products: * Belzona® 4131 (Magma Screed) ,
* Belzona® 2211 (MP Hi-Build) ,
* Belzona® 4151 (Magma Quartz Resins) ,

Customer Location: Hospital in North Carolina, U.S.A.
Application Date: Winter 2000

Problem

The metal expansion joint in the kitchen of this hospital had failed and the deterioration caused interruption in cart movement over the irregular sur-face.



Photograph Descriptions

- * Damaged metal expansion joint ,
- * Finished application with Belzona® 4151 recently applied ,
- * Nosing fully cured and ready for traffic ,

Application Situation

Metal expansion joint or slip joint in hospital kitchen floor.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-5 and FPA-6.

Belzona Facts

The red Belzona® 4131 (Magma Screed) gives the repair area a close color match to the original quarry tile floor.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve